

GREG BELL Lieutenant Governoi

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER **Executive Director**

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representatives Present During the Inspection:							
Company	Dennis Ware						
OGM	Steve Demczak						

Inspection Report

Permit Number:	C0070004
Inspection Type:	PARTIAL
Inspection Date:	Monday, April 23, 2012
Start Date/Time:	4/23/2012 10:00:00 AM
End Date/Time:	4/23/2012 2:00:00 PM
Last Inspection:	Friday, April 13, 2012

Inspector: Steve Demczak, Weather: Sunny, 50's

InspectionID Report Number: 3083

Accepted by: jhelfric 5/7/2012

Permitee: CASTLE GATE HOLDING CO Operator: CASTLE GATE HOLDING CO

Site: CASTLE GATE MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	7,619.00		
Total Disturbed	62.42		
Phase I	62.42		
Phase II	58.10		
Phase III			

Mineral Ownership

✓ Federal County Other

Types of Operations

✓ Underground ✓ Surface ✓ Loadout Processing Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violatios were issued.

The Permittee notified the Division that the required second quarter of 2011 surface water monitoring information for the Castle Gate Mine was in the DOGM EDI pipeline and was acceptable for uploading. The Permittee continues to meet the Special Condition included as Attachment "A" of the current State permit. There are no other "special" permit conditions.

The field conditions in Sowbelly and Hardscrabble Canyons remain virtually unchanged, as does the condition of the reclaimed area for Adit #1.

Inspector's Signature:

Date

Monday, Ap



Stephen & Demogak

Permit Number: C0070004 Inspection Type: PARTIAL

Inspection Date: Monday, April 23, 2012

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	V		✓	
3.	Topsoil	~		~	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		~	
8.	Noncoal Waste	~		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	✓		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	~		✓	
13.	Revegetation				
14.	Subsidence Control		✓		
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing	V		✓	
16.t	Roads: Drainage Controls	V		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070004 Inspection Type: PARTIAL

Inspection Date: Monday, April 23, 2012

Page 3 of 3

2. Signs and Markers

Identification signs are at the gates to the property.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

Diversion were opened and functioning as designed. No water was flowing within the diversion.

4.c Hydrologic Balance: Other Sediment Control Measures

The complete reclamation site was pocked for sediment control.

7. Coal Mine Waste, Refuse Piles, Impoundments

The site has been reclaimed and no inspections are required.

8. Noncoal Waste

The sites were free of non-coal waste materials.

10. Slides and Other Damage

No slides were noticed during the inspection.

12. Backfilling And Grading

The sites are completely reclaimed. All backfilled material was used.

16.a Roads: Construction, Maintenance, Surfacing

The road is graveled running through the property at Hardscrabble Canyon. There is no road at #5 Mine.

16.b Roads: Drainage Controls

No water was crossing the road through Hardscrabble.